



Connector shown from top view.
Pins shown as seen on electronic load.

Note J1 - Pin 2 and the (-) source under test are connected, never have current flowing through this path. All control signals should be connected to J1-pin 2.
Only the source under test should be connected to the power test terminal (+) and (-).



[Http://www.EXEC-ENG.com](http://www.EXEC-ENG.com)

Executive Engineering

Schematic is show with external slew capacitor

Title Remote Control Testing using pots

Size	Number	Rev
A	301/151 Remote Control	1
Date	Mon Sep 20, 2004	Drawn by dw
Filename	ext-pot:SCH	Sheet 1 of 1